

Table of Contents

OpenPort 2.0 adapter driver install 2

OpenPort 2.0 adapter driver install

1. Download the archive file with drivers, unzip it in a convenient place.

Download

2. Open Device Manager.
3. Connect the OpenPort adapter to the USB connector.




- Windows 7 8 10 can install drivers automatically. If this feature is not disabled in your Windows settings, then the driver must also be reinstalled manually.


4. Find a new device in the tree. Call the context menu by right-clicking. Click → Update drivers...




- При первом подключении адаптер может определяться Windows как устройство в разделе - Порты (COM и LPT). Устройство можно определить вставляя и вынимая USB шнур в разъем. Устройство которое будет пропадать и появляться в дереве Диспетчера устройств, будет соответствовать адаптеру. Именно у этого устройства нужно обновить драйвер на драйвер адаптера




5. Выбрать → Выполнить поиск драйверов на этом компьютере.




6. Нажать → Выбрать драйвер из списка уже установленных драйверов.




7. Нажать → Установить с диска → Далее.



8. Нажать → Обзор.



9. Выбрать файл установщик драйвера. Нажать → Открыть.



10. После процедуры установки драйвера, в Диспетчере устройств должен появиться адаптер OpenPort 2.0.

